

Scotchman Ironworkers

LEAD TIME (Weeks)	Model
1	Porta Fab 45
1	50514-EC
1	ELEC C
1	5014-ET
2 to 3	6509-24M
2 to 3	9012-24M
2 to 3	12012-24M
2 to 3	DO 70 /110-24
2 to 3	DO 95/140-24
2 to 3	DO 120/200-24M
2 to 3	DO 135/220-24M
2 to 3	DO 150/240-24M
2 to 3	FI 8510-20M
2 to 3	DO 8514-20M
2 to 3	ShearMaster 610

Scotchman Cold Saws

LEAD TIME (Weeks)	Model
2 to 3	CPO 350
2 to 3	CPO 350 PK
2 to 3	CPO 350 PK/PD
1	CPO 275
1	CPO 275 PK
1	CPO 275 PK/PD
2 to 3	CPO 350 NF
2 to 3	CPO 350 NF/PK
2 to 3	CPO 350 NF/PK/PD